Small size, High accuracy pressure control digital pressure sensor

Features

- · High accuracy digital pressure sensor
- High brightness red LED(LED height: 9.5mm)
- High resolution: 1/1000
- Convertible pressure unit
 - Negative pressure, Compound pressure: kPa, kgf/cm², bar, psi, mmHg, mmH₂O, inHg
 - Standard pressure : kPa, kgf/cm2, bar, psi
- Various output modes: Hysteresis mode, Automatic sensitivity setting mode, Independent 2 output mode, Window comparative output mode
- Chattering prevention for output (Selectable response time: 2.5, 5, 100, 500ms)
- Analog output(1-5VDC) scale function
- Reverse power polarity and overcurrent protection circuit
- · Zero-point adjustment function
- Peak and Bottom hold display

Ordering information





PSB Series

PSB Series

PSA Series

Connector type

Rc1/8 R1/8 Standard(PSA Series) Pressure port NPT1/8 Option(PSA Series) M5 Standard(PSB Series) Output type No mark NPN open collector output Р PNP open collector output Cable*1 No mark Positive(Cable integrated type) Connector type C 01 Pressure range 100kPa 1,000kPa 1 No mark Standard pressure Pressure type V Negative pressure С Compound pressure Regular square(30mm×30mm) Appearance A В Rectangular(10.2mm×54mm)

※1: It is only applied to PSB Series.

Item

Pressure and Max. pressure display range

		•	•				
Туре	kPa	kgf/cm ²	bar	psi	mmHg	inHg	mmH2O
							0.0 to -103.4 (5.2 to -103.4)
Standard			0.000 to 1.000 (-0.050 to 1.100)	0.00 to 14.50 (-0.72 to 15.96)	_	_	_
pressure				0.0 to 145.0 (-7.2 to 159.6)	_	_	_
Compound pressure		-1.020 to 1.020 (-1.034 to 1.122)			-750 to 750 (-760 to 824)	-29.5 to 29.5 (-29.8 to 32.6)	-102.0 to 102.0 (-103.4 to 112.2)

PS

Pressure Sensor

Pressure conversion chart

from to	Pa	kPa	MPa	kgf/cm ²	mmHg	mmH ₂ O	psi	bar	inHg
1Pa	1	0.001	0.000001000	0.000010197	0.007501	0.101972	0.000145038	0.000010000	0.0002953
1kPa	1000.000	1	0.001000	0.010197	7.500616	101.9716	0.145038	0.010000	0.2953
1MPa	1000000	1000	1	10.197162	7500.61683	101971.553	145.038243	10	295.299875
1kgf/cm ²	98066.54	98.066543	0.09806	1	735.5595	10000.20	14.22334	0.980665	28.95878
1mmHg	133.322368	0.133322	0.000133	0.001359	1	13.5954	0.019336	0.001333	0.039370
1mmH ₂ O	9.80665	0.00980	_	0.000099	0.0735578	1	0.00142	0.000098	0.002895
1psi	6894.757	6.89757	0.00689	0.070307	51.71630	703.07	1	0.068947	2.036003
1bar	100000.0	100.0000	0.100000	1.019689	750.062	10196.89	14.50339	1	29.52998
1inHg	3386.417	3.388418	0.003386	0.034532	25.40022	345.31849	0.491158	0.033863	1

Ex) For calculating 760mmHg as kPa: According to above chart, 1mmHg is 0.133322kPa, therefore 760mmHg will be 760×0.133322kPa=101.32472kPa.

(A) Photo electric sensor

(B) Fiber optic sensor

(C) Door/Area sensor

(D) Proximity

(G) Connector/ Socket

(I) SSR/

(K) Timer

(M) Tacho/ Speed/ Pulse meter

(N) Display unit

(P) Switching mode powe supply

motor& Driver&Co

Logic

F-17

X() is Max. pressure display range.

[※]For using a unit mmH₂O, multiply display value by 100.

PSA / PSB Series

Specifications


D		Gauge pressure			
Pressur	е туре	Negative pressure	Standard pressure		Compound pressure
Model	NPN open collector output	PSA-V01- □ PSB-V01- □ PSB-V01C- □	PSA-01- □ PSB-01- □ PSB-01C- □	PSA-1- □ PSB-1- □ PSB-1C- □	PSA-C01-□ PSB-C01-□ PSB-C01C-□
*1	PNP open collector output	PSA-V01P- □ PSB-V01P- □ PSB-V01CP- □	PSA-01P- □ PSB-01P- □ PSB-01CP- □	PSA-1P- □ PSB-1P- □ PSB-1CP- □	PSA-C01P- □ PSB-C01P- □ PSB-C01CP- □
Rated p	ressure range	0.0 to -101.3kPa	0.0 to 100.0kPa	0.0 to 1,000kPa	-100.0 to 100.0kPa
Display	and set pressure range	5.0 to -101.3kPa	-5.0 to 110.0kPa	-50 to 1,100kPa	-101.2 to 110.0kPa
Max. pr	essure range	2 times of rated pressure		1.5 times of rated pressure	2 times of rated pressure
Applied	fluid	Air, Non-corrosive gas			
Power s	supply	12-24VDC ±10%(Ripple F	P-P : Max. 10%)		
Current	consumption	Max. 50mA			
Control	<u>'</u>	NPN or PNP open collect • Load voltage: Max. 30VE		100mA • Residual voltage - NP	N: Max. 1V, PNP: Max. 2V
Hyste	eresis ^{×2}	1digit fixed(2digits for psi	unit)		2digit fixed
Repe	eat error	±0.2% F.S. ±1digit			±0.2% F.S. ±2digit
Resp	onse time	Selectable 2.5ms, 5ms, 1	00ms, 500ms		
Short	circuit protection	Built-in			
Analog	output	Output voltage: 1-5VDCLinear: Within ±2% F.S.		: Within 1VDC ±2% F.S. • Spar : Approx. 1/200 • Outp	n: Within 4VDC ±2% F.S. out impedance: 1kΩ
Display	digit	3½digit			
Display	method	7Segment LED			
Min. dis	play interval	1digit(psi unit: 2 digits are	fixed)		2digits
Pressur	e unit	kPa, kgf/cm² , bar, psi, mmHg, mmH ₂ O, inHg	kPa, kgf/cm², bar, psi		kPa, kgf/cm², bar, psi, mmHg, mmH2O, inHg
	accuracy	0°C to 50°C: Max. ±1% F.		6 F.S.	
Environ-	Ambient temperature	-10 to 50°C, storage: -20	to 60°C		
ment	Ambient humidity	35 to 95%RH, storage: 35	5 to 95%RH		
HOHL					
	n	1.5mm amplitude at frequ	ency of 10 to 55Hz(for 1	min.) in each of X, Y, Z direction	ns for 2 hours
Vibratio			ear case: PC(Insert glas	min.) in each of X, Y, Z directions), Pressure port: die-cast(Zn)	ns for 2 hours
Vibratio Materia	l	PSA: Front case: PC, Re PSB: Case, Pressure po	ear case: PC(Insert glas		ns for 2 hours
Vibratio Materia Protecti Cable	l	PSA: Front case: PC, R. PSB: Case, Pressure pc PSB-C: Case, Pressure IP40(IEC standard) Ø4, 5-wire, Length: 2m	ear case: PC(Insert glas ort: PA port, Cover: IXEF		
Vibratio Materia Protecti	on	PSA: Front case: PC, R. PSB: Case, Pressure pc PSB-C: Case, Pressure IP40(IEC standard) 4, 5-wire, Length: 2m (AWG24, Core diameter: 5-wire, Length: 3m(AWG	ear case: PC(Insert glas ort: PA port, Cover: IXEF 0.08mm, Number of core	s), Pressure port: die-cast(Zn) es: 40, Insulation out diameter:	
Vibratio Materia Protecti	on Cable integrated type Connector type	PSA: Front case: PC, R. PSB: Case, Pressure pc PSB-C: Case, Pressure IP40(IEC standard) 4, 5-wire, Length: 2m (AWG24, Core diameter:	ear case: PC(Insert glas ort: PA port, Cover: IXEF 0.08mm, Number of core	s), Pressure port: die-cast(Zn) es: 40, Insulation out diameter:	

Analog output voltage-Pressure characteristic

PSA-01 Output 6 voltage (V) 5 4 3 2 0 20 80 100 Pressure(kPa)

• Analog output voltage-Linear characteristic

※F.S.: Rated pressure.



E-18 **Autonics**

X1: '□' is pressure port type.


X2: In hysteresis output mode, detection difference is variable.

XThere may be ±1digit error in hysteresis by pressure unit calculation error.

XThe specification of pressure port is marked on the upper part of the case.

Pressure ports are distinguished by the colors, silver [Rc(PT)1/8] or black [NPT1/8].

XEnvironment resistance is rated at no freezing or condensation.




Autonics E-19

Control output diagram(PSA/PSB)

• NPN open collector output type


(Brown)+V (Orange)Analog voltage output Load Negative (Black)OUT1 (White)OUT2 T 12-24VDC (Blue)0V

PNP open collector output type



- *There is no short-circuit protection in analog voltage output. Do not connect this output to power supply or capacitive load directly.
- XPlease observe input impedance of connected equipment when use analog voltage output. And be sure to check voltage drop caused by resistance of extended wire.

■ Front panel identification



- 1. 31/2 digit LED display(red)
 - : Display sensing pressure, every setting value and display error.
- 2. 1 output indicator(red): Output 1 is ON, LED will be ON.
- 3. 2 output indicator(PSA: red, PSB: green)
 - : Output 2 is ON, LED will be ON.

4. Mode key

: Parameter setting mode or preset setting mode, save setting value.

5. Up key

: Set the setting value to lower step in preset setting or pressure unit, output mode, response time, analog output scale, key lock, peak hold value, bottom hold value display in parameter setting.


6. Down key

: Set setting value to upper step in preset setting or pressure unit, output mode, response time, analog output scale, key lock, peak hold, bottom hold display in parameter setting.


7. Range of rated pressure

: It is possible to change the pressure unit in PSA Series. Please use different unit as label for your application.

Setting(PSA/PSB)



Zero point adjustment(PSA/PSB)




- In state of atmospheric pressure during RUN mode, press ▼ key and ▲ key at the same time for over 1sec.
- When the zero point adjustment is completed, it will display @@ and return to RUN mode automatically.
 Please execute zero point adjustment regularly.



If executing zero point adjustment when external pressure has been applied, Er I will be flashing. Please execute zero point again in state of atmospheric pressure.

Pressure Sensor

■ Parameter setting(PSA/PSB)



※Key lock functions

- L o C : Disable to change preset value and parameter value (Enable to change P E 9 mode only)
- PRL: Enable to change preset value, disable to change parameter value
- $\mbox{U}_{\mbox{\scriptsize nL}}$: Enable to change preset value and parameter value(Lock off)

Photo electric sensor

(B) Fiber optic sensor

(C) Door/Area sensor

(D) Proximity

(E) Pressure

>) otary

(G) Connector/ Socket

(H) Temp.

(I) SSR/ Power

(J) Counter

(K) Timer

>) anel

(M) Tacho/ Speed/ Pulse meter

(N) Display unit

))

(O) Sensor controller

(P) Switching mode power supply

(Q) Stepper motor& Driver&Controller

Driver&Controlle

(R) Graphic/ Logic panel

(S) Field network device

device

Oitware

J) ther

Autonics E-21

<sup>When advance to parameter setting mode and preset setting mode, it displays "Setting item" and "Previous setting value" by 0.5 sec. turn. This display will stop by pressing
or ▲ key(Display setting value), if any key is untouched for over 1 sec., it will display old value by 0.5 sec. turn again.</sup>

^{*}When M key is pressed for 3sec. during setting, it will return to RUN mode with memorizing on EEPROM. However, when there is any key is untouched for 60sec., it turns to RUN mode with keeping the previous setting value not current setting value.

^{**}There is memory protection by EEPROM, but life cycle of EEPROM is 100,000 times.

Preset value setting(PSA/PSB)

⊕ Hysteresis mode[F-1] and independent 2 output mode[F-3,F-4,F-5]













5 ! and previously set value will flash in turn every 0.5 sec.



Press ▼ or ▲ Kev to select 5 + 1 setting 5 t 2 and previously set value will flash in turn every 0.5 sec.



Press ▼ or ▲ Kev to select 5 £ 2 setting value

※5₺ / setting range : Min. display pressure < 5₺ / ≤ Max. display pressure
</p> X5£2 setting range: - Hysteresis mode: Min. display pressure ≤ 5£2 < 5£1.
</p>

- 2 independent output mode: Min. display pressure < 5 t ≥ ≤ Max. display pressure


















5 t and previously set value will flash in turn every 0.5 sec



After applying 5 ± 1 into Pressure port, then press ▲ Key.



After applying 5 £ 2 into Pressure port, than press ▲ Key.



Sensitivity will be automati-Press ▼ or ▲ key to fineadjust the setting value bet-

ween 5t 1 and 5t2 5t 1+5t2


※5₺2 setting range: 5₺ / + 1% of rated pressure <5₺2 ≤ Max. display pressure
</p>

Adjustable range of set value: Between 5£ 1 and 5£2.

○ Window comparison output mode[F-6]













HI and previously set value will flash in turn every 0.5 sec.



Press or Key to select Lo setting value.



Press ▼ or ▲ Key to select HI setting value.

XLow value setting range: Min. display pressure < L □ ≤ Max. display pressure
</p>

- If no key is touched for 60sec., it will return to RUN mode. [Automatic sensitivity setting mode[F 2] is exception]
- When changing the display unit, preset value will be calculated according to the display unit.
- Whenever key touched one time, it is increased(decreased) as 1 digit(2 digits for psi unit and compound pressure) but it will be continuously increasing(decreasing) by pressing ▼, ▲ key constantly.

Peak hold and bottom hold check

- 1. Press kev for over 3sec. in RUN mode.
- 2. PEH and memorized max. pressure(Negative pressure type is for max. negative pressure) will flash by turning on (0.5sec.) then display peak hold value.
- 3. baH and memorized min. pressure(Negative pressure type is for min. negative pressure) will flash by turning on (0.5sec.) then display bottom hold value.
- 4. If pressing A key one time shortly, memorized peak hold and bottom hold value will be removed then return to RUN mode.
- *When the peak hold and bottom hold value is over the max. display pressure value, it displays HHH, On the opposite, it displays LLL. Please remove peak hold and bottom hold value by using A key.

■ Output operation mode(PSA/PSB)

1. Hysteresis mode [F-1]

XIt can be set for pressure sensing level[5½ 1] and sensing difference[5½2].


: Min. display pressure < 5 $\vdash 1$ \le Max. display pressure

5 £ 2 setting range

: Min. display pressure ≤ 5 £ 2 < 5 £ 1

• OUT 1: When applying pressure is larger than 5£ 1, it wil be ON.

• OUT 2: When applying pressure is lower than 5 £ 2, it will be ON.



2. Automatic sensitivity setting mode [F-2]


※This function is to set pressure sensing level to the proper position automatically, it is set by received pressure from two positions [5₺ 1,5₺2].

*The sensing hysteresis fixed to 1 digit(2 digits for psi unit and compound type)

*The pressure sensing level [5EE] is shown in the following calculation. $5EE = \frac{(5EI + 5EE)}{2EE}$

 OUT 1: When applying pressure is larger than 5EŁ value, it will be ON.

 OUT 2: When applying pressure is between 5₺ 1 and 5₺ ², it will be ON.



Note1) If it is not enough for difference of sensing level between 5 £ 1 and 5 £ 2, £ r 3 will be displayed. Please set again after applying enough pressure.

Note2) 5 \(\) \(\) setting range: Min. display pressure <5 \(\) \(\) \(\) Max. display pressure -1% of rated pressure 5 \(\) \(\) ≥ setting range: 5 \(\) \(\) \(\) \(\) \(\) \(\) frated pressure \(\) \(\) \(\) \(\) \(\) \(\) Ax. display pressure

Note3) If fine adjustment for sensing level is required, adjust sensing level by , ▲ key. (Adjustment range: Between 5 ≥ 1 and 5 ≥ 2)

3. Independent 2 output mode [F-3, F-4, F-5]

※5Ł I and 5Ł 2 can be set independently within display pressure range. One is for control, the other is for alarm or optional control.

**The sensing hysteresis fixed to 1 digit(2 digits for psi unit and compound type)

: Min. display pressure $\leq 5 \pm 1 \leq$ Max. display pressure 5 ± 2 setting range

: Min. display pressure $\leq 5 \, \ell \, \geq \, \text{Max.}$ display pressure

• Independent 2 output mode [F - ∃]

• OUT 1: It will be ON, when it is over 5£ 1.

• OUT 2: It will be ON, when it is over 5 t 2.

• Independent 2 opposite mode [F - 4]


• OUT 1: It will be OFF when it is over 5t 1.

• OUT 2: It will be OFF, when it is over 5 t 2.

• Independent 2 cross mode [F - 5]

• OUT 1: It will be OFF when it is under 5£ 1.

• OUT 2: It will be ON, when it is under 5 £ 2.



4. Window comparison output mode [F-6]


※It is able to set High limit value [HI], Low limit value [L□] of pressure sensing level in this mode.

**The sensing hysteresis fixed to 1 digit(psi unit and compound type 2 digits)

: Min. display pressure ≤ L □ ≤ Max. display pressure
HI setting range : L □ < HI ≤ Max. display pressure

 OUT 1 : It will be ON between high limit value[HI] and low limit value[LD]

• OUT 2 :It will be ON when it is over high limit value[HI] and low limit value[L a].



(A) Photo electric sensor

(B) Fiber optic sensor

> (C) Door/Area sensor

> (D) Proximity



(F) Rotary encoder

(G) Connector/ Socket

(H) Temp. controller

(I) SSR/ Power controller

(J) Counter

(K) Timer

meter
(M)

(M)
Tacho/
Speed/ Pulse
meter

(N)
Display
unit

(O) Sensor

(P) Switching mode power supply

(Q) Stepper motor& Driver&Controller

Graphic/ Logic panel

(S) Field network device

(T) Software

(U) Other

Autonics E-23

Functions(PSA/PSB)

O Pressure unit change

PS \square -V01(C)(P)/PS \square -C01(C)(P) has 7 kinds of pressure unit and PS \square -01(C)(P)/PS \square -1(C)(P) has 4 kinds of pressure unit.

Please select the proper unit for application.

- PS_-V01(C)(P), PS_-C01(C)(P):
- kPa, kgf/cm², bar, psi, mmHg, inHg, mmH₂O

Output mode change

There are 6 kinds of control output modes in order to provide the various detection. Select a mode for your proper application.

• Hysteresis mode [F-1]

When variable hysteresis is required for pressure detection.

• Automatic sensitivity setting mode [F-2]

When it is required to set detecting sensitivity automatically at proper position.

• Independent 2 output mode [F-3,F-4,F-5]

When it is required to detect pressure from two position with one product.

• Window comparison output mode [F-5]

When is required to detect pressure in a certain range.

Response time change (chattering prevention)

It can prevent chattering of control output by changing response time. It is able to set 4 kinds of response time(2.5, 5, 100, 500ms) and if the response is getting longer, the sensing will be more stable by increasing the number of digital filter.

Analog output scale setting

It is not fixed the analog output(1-5VDC) scale as the rated pressure range but this is a function to change properly for user's application. When the position[R-1] for 1VDC output and the position [R-5] for 5VDC output are set, the pressure range of R-1 to R-5 is to 1-5VDC analog output.

Key lock

This unit has 2 kinds of key lock function in order to prevent wrong operation.

- Lp[: All keys are locked, it is impossible to change any parameter setting/preset, zero point adjustment, peak hold and bottom hold. (Enable to change PEY mode only).
- PAL: This is partial locked status, it is impossible to change parameter setting. (Enable to change PEY mode only).
- ปกL: All keys are unlocked.

Zero-point adjustment

This function is to set the display value of pressure at zero when port is opened to atmospheric pressure.

O Peak hold and bottom hold


This function is diagnosis malfunction of the system caused by parasitic pressure or to check through memorizing the max./min. pressure that occurred in the system.

© Error display


Error display	Description	Troubleshooting
Erl	When external pressure is input while adjusting zero point	Try again after removing external pressure
E-2	When overload is applied on control output	Remove overload
Er3	When the setting value is not matched with setting condition	Check setting conditions and set proper setting values
ннн	When applied pressure exceeds High-limit of display pressure range	Apply pressure within
LLL	When applied pressure exceeds Low-limit of display pressure range	display pressure range

Installation (PSA Series)


- When installing pressure port, it is able to bring pressure from 3 directions by changing the mounting direction of the pressure port.
- Basic spec of pressure port is Rc(PT) 1/8"(color: Silver). [option:NPT 1/8(color: black)] It is able to use general one touch fitting.



- 3. Please use seal tape at port plug in order to prevent pressure leak.
- 4. Please block another two pressure ports not used with port plug.



Please connect it by using spanner(13mm) at the metal part in order not to overload on the body when connecting one touch fitting.



∧Caution


Autonics

The tightening torque of one touch fitting should be max.100kgf·cm. If not, it may cause mechanical problem.

E-24

Pressure Sensor


- 6. PSA Series has 2 kinds of brackets so it is able to install it in two different ways.
- 7. At first, please unscrew hexagon wrench bolt and assemble the bracket on this unit by fixing the hexagon wrench bolt.



⚠Caution


In this case, tightening torque of hexagon wrench should be max. 30kgf·cm. If not, it may cause mechanical problem.

8. Bracket(PSO-01) and front protection cover(PSO-02) are sold separately. Please see the pictures for installation.




Installation(PSB Series)


1. Pressure port is M5. Use general one touch fitting.



2. It is able to use it without the pressure port according to environment. In this case O-Ring between pressure port and its body should not be taken out in order to prevent pressure leak



3. Please connect it by using spanner(10mm) at pressure port in order not to overload on the body when connecting one touch fitting



∴Caution


The tightening torque of one touch fitting and hexagon wrench should be Max. 50kgf·cm and 20kgf·cm. It may cause mechanical trouble. Please do not use spanner to install as it may cause mechanical trouble.

Proper usage


∧Caution

PSA, PSB Series is for sensing of non corrosive gas. Do not use this product at corrosive gas or flammable gas, etc.

- · Please using this unit within the range of specification, if applying pressure is larger than specification, it may not be working properly due to damage.
- · After supplying power, it takes 3 sec. to work.
- · When using switching mode power supply, frame ground (F.G.) terminal of power supply should be grounded.



- · It may cause malfunction by noise, when wiring with power line or high voltage line.
- · Do not insert any sharp or pointed object into pressure port. It may cause mechanical problem due to sensor damage.
- Do not use this unit with flammable gas, because this is not an explosion proof structure.
- · Be sure that this unit should not be contacted directly with water, oil, thinner, etc.



· Wiring must be done with power off.

Accessory

PSA/PSB


Pressure unit label

±100kPa ±101.3kPa 100kPa 1MPa						
±1.020kgf/cm²	-1.034kgfilan	1.020kgf/or	10.20kgf/cm			
±14.50psi	-14.70psi	14.50psi	145.0psi			
±1.000bar	-1.013bar	1.000bar	10.00bar			
±750nnhg	-760mmhg	×10	×10			
±29.5inHg	-29.9inHg	×100	×100			
±102.0mmH ₂ O	-103.4mmH ₂ O	×1000	×1000			
DISPLAY UNIT LABEL						

Only for PSA Series

Port plug

Bracket A



senso

(B) Fiber optic sensor

(C) Door/Area sensor

(D) Proximity

(I) SSR/

(K) Timer

(M) Tacho/ Speed/ Pulse meter

(N) Display unit

(P) Switching mode power

Logic

(T) Software

F-25 **Autonics**